




Basic features

Principle of operation	Mounting bracket for photoelectric sensor
Scope of delivery	Mounting brackets Nut ISO 4032-M3 (2x) Washer ISO 7089-M3 (4x) Screw ISO 7045-M3x16 (2x)
Short description	Mounting brackets
Use	for photoelectric sensors BOS 18KF for photoelectric sensors BOS 18KW

Version	2 adjustable axes
---------	-------------------

Material

Material	Steel
Surface protection	Zinc plated

Mechanical data

Dimension	20 x 35 x 35 mm
Mounting part	Screw M4